



MYSORE URBAN DEVELOPMENT AUTHORITY

NO.MUDA/Zone-5A/2016-17

Date : 23.03.2017

CERTIFICATE OF LAND

Certified that land measuring 8094 sq. Mts of site No-B, equivalent to 2 acres 02 Guntas Situated in Bannimantap 'B' Layout, Shivaratreshwaranagar, Mysore City, Mysore District, Karnataka State fully Described in the Schedule mentioned here in after is Leased to Majlis-e-Rifahul Muslimeen in terms of allotment and Possession certificate issued from Mysore Urban Development Authority, Mysore. Dated 19.04.1989, Executed by Chairman Mysore Urban Development Authority, Mysore. Duly registered on 21.09.1999 at Serial No-119 in book NO-KBW/ REG/22/Mys/89-99 It is Certified that the said entire land comprises of a single plot of land,

THE SCHEDULE LAND ABOVE REFERRED TO

All that piece and parcel of land site No-B, Measuring 8094sq, Mts equivalent 2 acres 02 Guntas Situated in Bannimantap 'B' Layout, Shivaratreshwaranagar, Mysore City, Mysore District, Karnataka and Bounded as follows.

North - 30' Ft Road
South - 40' Ft Road
East - 30' Ft Road
West - 40' Ft Road


Commissioner 23/3/17
COMMISSIONER
Mysore Urban Development Authority
Mysore
MYSORE.


MANAGER
Majlis-e-Rifahul Muslimeen


Principal
HUDA PUBLIC SCHOOL

BUILDING SAFETY CERTIFICATE

No. E.E:PWD:MYDMY:AE-4:Renewal:2024-25

Dated: 09.10.2024

Certified that the existing building or premises) at **HUDA PUBLIC SCHOOL** (name of the building or premises) at No 48, Rifah Campus, Bannimantap 'B'layout, SS Nagar, Mysore 570015 (address) comprised of **One** basement(s) and **Three** (upper floors) owned/occupied by **HUDA PUBLIC SCHOOL**(name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Office of the Executive Engineer, Mysore Division, Mysuru** (Name of Department/ Govt.) on **27-09-2024** (date of Inspection) in the presence of **Sri. MUSHTAQ BAIG, Manager** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy up to classes **X (X)** and hence the **building safety certificate** is renewed for the year **2024-25** with effect from **15.10.2024 to 14.10.2025** for a period of **one** year in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.

Issued on **09-10-2024** at Mysuru by

- Strike out whichever is not applicable.

Signature with Seal: _____

Name: _____


Designation: _____

Name & Address of Department/ Office: **Public Works Department**
 (Assistant Engineer & above officer of concerned Govt. Department only) **Mysuru Division, Mysuru-570 005**

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English is uploaded along with the original vernacular certificate as a single pdf.


MANAGER
 Majlis-e-Rifahul Muslimeen


Principal
HUDA PUBLIC SCHOOL

GOVERNMENT OF KARNATAKA

PUBLIC WORKS DEPARTMENT

OFFICE OF THE EXECUTIVE ENGINEER, MYSORE DIVISION, MYSORE.

www:eepwdmys21@gmail.com.

Telephone No./0821 2420810

Fax No.

NO. EE/PWD/MDMY/AE/Building Security:2024-25 /3758-3759/

To: 9-10-2024

The Secretary,
Majlis-e-Rifhul Muslimin
Huda Public School,
No.48, Rifha Campus,
S. S. Nagar,
J. S. S. Dental College Behind,
Bannimantap B-Layout,
Mysore-570 015.

Sir,

Sub: Request for issue of Building Security Certificate to Huda Public School, No.48, Righa Campus, S.S. Nagar, J.D.S. Dental College Behind, Bannimantap 'B' Layout, Mysore.

- Ref: 1. Your Letter Dated: 20-9-2024
2. Letter No. 773-74 Dated: 3-10-2024 of Asst. Executive Engineer, PW.D, No.1, Sub-Division, Mysore .
3. Government Circular No. PWD/59/BED/2019, Dated 6-5-2022.
4. This office Letter No. 3750/ 9-10-2024.

With reference to the above, the Assistant Executive Engineer, No.1, Sub-Division, Mysore has verified and supervising School Building at Hudha Public School, No.48, Rifah Campus, S. S. Nabar, J. S. S. Dental College Behind, Bannimantap B-Layout, Mysore as per above cited reference No.1. The said A. E. E., Mysore has given the report as Build Point Construction and Technologies, Gangathri Layout, Mysore as ISO/IEC National Building Code 2016 Group-B (Sub-Division B1 and B2) Education Building with NDTText and Structural Stability Certificate including technical report in

E. N. Nataraj
Principal
HUDA PUBLIC SCHOOL

J. B. P.
MANAGER
Majlis-e-Rifahul Muslimeen

..2..



in the form of Annexure of spot Inspection of the Building on 27-9-24 to this office. The Asst. Executive Engineer P.W.D. No.1, Sub-Division, Mysore has verified and certified the same as per Ref.No.2.

The Said building has physically inspected on 27-9-2024. The building was completed in the year 2010 has informed by the school Authority. The Said building was constructed in the form of Cellor, Ground Floor, First Floor, second floor and 3rd Floor. The said Building is fully stability condition as per report of the N.D.T. report. In this building has got dring water facility, Toilet Facility was also done, and this building was fit for Education Purpose, as per report of the Buildpoint Constructions and Technoligies, Gangothri Layout, Mysore and also certified the building was in Stability Condition as Reported by the Asst. Executive Engineer, P.W.D. No.1 sub-Division, Mysore the same has been certified by the AEE.

Incontinuation of this the said Assistant Executive Engineer, No.1, Sub-Division, Mysore, has informed about the structural stability about the said building as reference cited about, as per report of Physical Observ-ation and Accordingly necessary field Tests for the said building and same has been discussed with Technicians of Sub-Division Office, and the said building is fully Stable as per report given by them.



[Signature]
Principal
MUDA PUBLIC SCHOOL

[Signature]
MANAGER
Majlis-e-Rifahul Muslimeen

:3:

Recognizance, Visual inspection of Building -Cracks, distress, Dampness etc., these examinations are inspected with Jointly by Buildpoint Constructions and Technologies , Gangothri Layout, Mysore and Public Works Department Technicians.

Build Point Constructions and Technologies , Gangothri Layout, Mysore has issued a Form for Certificate for Structural Design Sufficiency Certificate.

The said school Trust has paid the fixed Fee of Rs. 5,000/- to Accounts Branch as per Karnataka Government Circular No. PWD/59/BED/2019 Dated: 6-5-2022, and the said building was Structural Stability is good as stated by the Build Point Constructions and Technologies, Gangothri Layout, Mysore and issued the certificate by them, the said building has been verified and inspected by Physically and stated as the said school building is in Fully stability Safety and is sufficient to use the building as Certified by the office. Hence, this Office issued a Building Safety Certificate for running of school for the Academic Year of Education.

Yours faithfully,

sd/-

Executive Engineer,
Public Works Depart, ent.
Mysore Division,
Mysore.

The Original Document in ^{KANNADA}
is translated to ENGLISH
and the translation is Verified by me
as true and Correct.


MANAGER
Majlis-e-Rifahul Muslimeen




Principal
HUDA PUBLIC SCHOOL


Notary Mysore

6 NOV 2021



ಸಂಖ್ಯೆ :ಕಾಇಂ:ಲೋಇ:ಮೈವಿಮೈ: ಸ ಇಂ-4: ಕಟ್ಟಡ ಸುರಕ್ಷತೆ: 2024-25
ರವರಿಗೆ

3758-3759
09/10/2024

ಕಾರ್ಯದರ್ಶಿಯವರು,
ಮಜ್ಲಿಸ್-ಇ-ರಿಫಾಹುಲ್ ಮುಸ್ಲಿಮೀನ್,
ಹುದಾ ಪಬ್ಲಿಕ್ ಶಾಲೆ, # 48, ರಿಫಾ ಕ್ಯಾಂಪಸ್,
ಎಸ್.ಎಸ್. ನಗರ,
ಜೆ.ಎಸ್.ಎಸ್. ಡೆಂಟಲ್ ಕಾಲೇಜು ಹಿಂಭಾಗ,
ಬನ್ನಿಮಂಟಪ, ಬಿ ಬಡಾವಣೆ,
ಮೈಸೂರು 570 015.

ಮಾನ್ಯರೇ,

ವಿಷಯ : ಮೈಸೂರು ನಗರದ ಹುದಾ ಪಬ್ಲಿಕ್ ಶಾಲೆ, # 48, ರಿಫಾ ಕ್ಯಾಂಪಸ್, ಎಸ್.ಎಸ್. ನಗರ,
ಜೆ.ಎಸ್.ಎಸ್. ಡೆಂಟಲ್ ಕಾಲೇಜು ಹಿಂಭಾಗ, ಬನ್ನಿಮಂಟಪ, ಬಿ ಬಡಾವಣೆ, ಮೈಸೂರು,
ಇವರ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ :
1. ತಮ್ಮ ಪತ್ರ ದಿನಾಂಕ 20.9.2024.
 2. ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ನಂ.1 ಉಪ ವಿಭಾಗ, ಮೈಸೂರು, ಇವರ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 773-74 ದಿನಾಂಕ
03.10.2024.
 3. ಸರ್ಕಾರಿ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ:59:ಬಿಇಡಿ:2019 ದಿ. 06.05.2022.
 4. ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 3750 ದಿನಾಂಕ 09.10.2024.

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖ (1)ರಲ್ಲಿ ತಾವು ನಗರದ ಹುದಾ ಪಬ್ಲಿಕ್ ಶಾಲೆ, # 48, ರಿಫಾ ಕ್ಯಾಂಪಸ್, ಎಸ್.ಎಸ್. ನಗರ, ಜೆ.ಎಸ್.ಎಸ್. ಡೆಂಟಲ್ ಕಾಲೇಜು ಹಿಂಭಾಗ, ಬನ್ನಿಮಂಟಪ, ಬಿ ಬಡಾವಣೆ, ಮೈಸೂರು, ಕಟ್ಟಡವನ್ನು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.1 ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿದ್ದು, Build point Constructions and Technologies, Gangothri Layout, Mysore ರವರು ISO/IEC National Building Code 2016 Group B (Sub Division B1 and B2) Education Building ರನ್ವಯ NDT test & Structural Stability Certificate ಹಾಗೂ ತಾಂತ್ರಿಕ ವರದಿಗಳೊಂದಿಗೆ ನಿಗದಿತ ನಮೂನೆಯಲ್ಲಿ ವರದಿಯನ್ನು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಯನ್ನು ದಿನಾಂಕ 27.09.2024 ರಂದು ಸ್ಥಳ ಪರಿಶೀಲಿಸಿ ಉಲ್ಲೇಖ (2) ರಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1 ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

ಸದರಿ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ 27.09.2024 ರಂದು ಭೌತಿಕವಾಗಿ ಪರಿಶೀಲಿಸಲಾಗಿ, ಸದರಿ ಕಟ್ಟಡವು 2010 ರಲ್ಲಿ ಪೂರ್ಣಗೊಂಡಿರುವುದಾಗಿ ಶಾಲಾ ಮಂಡಳಿಯವರು ತಿಳಿಸಿದ್ದು, ಕಟ್ಟಡವು ನೆಲ ಮಳಿಗೆ ಮತ್ತು ನೆಲ ಮಹಡಿ ಮೊದಲನೇ ಮಹಡಿ, ಎರಡನೇ ಹಾಗೂ ಮೂರನೇ ಮಹಡಿಯ ಕಟ್ಟಡವಾಗಿರುತ್ತದೆ. ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವು ಎನ್.ಡಿ.ಟಿ. ವರದಿಗಳಂತೆ ಸುರಕ್ಷಿತವಾಗಿದ್ದು, ಅವಶ್ಯವಿರುವ ಕುಡಿಯುವ ನೀರಿನ ವ್ಯವಸ್ಥೆ, ಶೌಚಾಲಯ ವ್ಯವಸ್ಥೆಯನ್ನು ಮಾಡಲಾಗಿದ್ದು, ಶೈಕ್ಷಣಿಕ ಚಟುವಟಿಕೆಗೆ ಯೋಗ್ಯವಾಗಿರುತ್ತದೆ ಎಂದು Buildpoint constructions and Technologies, Gangothri Layout, Mysore, ರವರು ಹಾಗೂ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1 ಉಪವಿಭಾಗ, ಮೈಸೂರು, ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿರುವ ಬಗ್ಗೆ ಹಾಗೂ ಎಲ್ಲಾ ರೀತಿಯ ಸೌಲಭ್ಯಗಳನ್ನು ಹೊಂದಿರುವ ಬಗ್ಗೆ ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

Principal
HUDA PUBLIC SCHOOL



"TRUE COPY"
Compared with the original
and found correct

NOTARY, MYSURU DISTRICT

MANAGER
Majlis-e-Rifahul Muslimeen


ಮುಂದುವರೆದು, ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.1, ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ಉಲ್ಲೇಖ ಪತ್ರದಲ್ಲಿ ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ **Buildpoint Constructions and Technologies, Gangothri Layout, Mysore** ಇವರ Physical observation & Accordingly necessary field Tests ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಂಡು, ಸಮಾಲೋಚಕರೊಂದಿಗೆ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ವರ್ಗವು ನಡೆಸಿರುವ ಪರೀಕ್ಷೆಯ ವರದಿಯಂತೆ ಕಟ್ಟಡವು ಸದೃಢತೆಯಿಂದ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಎಂದು ವರದಿ ಮಾಡಿರುತ್ತಾರೆ.

Recognizance, visual inspection of Building-cracks, distress, dampness etc. ಪರೀಕ್ಷೆಯನ್ನು **Buildpoint Constructions and Technologies, Gangothri Layout, Mysore** ರವರ ಜೊತೆ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡದೊಂದಿಗೆ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ.

- Form for Certificate for Structural Design Sufficiency ಪ್ರಮಾಣ ಪತ್ರವನ್ನು **Buildpoint Constructions and Technologies, Gangothri Layout, Mysore** ರವರು ನೀಡಿರುತ್ತಾರೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ:59:ಬಿಇಡಿ:2019 ದಿನಾಂಕ 06.05.2022. ರಂತೆ ಸದರಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪಡೆಯಲು ನಿಗದಿಪಡಿಸಿರುವ ಶುಲ್ಕವಾದ ರೂ. 5,000.00 ಗಳನ್ನು ಲೆಕ್ಕಶಾಖೆಗೆ ಪಾವತಿಸಿರುವುದರಿಂದ, ಮತ್ತು **Buildpoint constructions and Technologies, Gangothri Layout, Mysore**, ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಸಲ್ಲಿಸಿರುವುದರಿಂದ, ಹಾಗೂ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.1, ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ದಿನಾಂಕ 27.09.2024 ರಂದು ಭೌತಿಕವಾಗಿ ಸ್ಥಳ ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದ್ದು, ಪ್ರಸ್ತುತ ಕಟ್ಟಡವು ಉಪಯೋಗಕ್ಕೆ ಯೋಗ್ಯವಾಗಿರುತ್ತದೆ ಎಂದು ದೃಢೀಕರಿಸಿರುವುದರಿಂದ, ಪ್ರಸಕ್ತ ಶೈಕ್ಷಣಿಕ ಸಾಲಿಗೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು (Building Safety Certificate) ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,


ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ
ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು.



"TRUE COPY"
Compared with the original
and found correct

NOTARY MYSURU DISTRICT


Principal
HUDA PUBLIC SCHOOL

MANAGER
Majlis-e-Rifahul Muslimeen